


# Chainless Conveyor

## FL-S



### POINTS

- No necessary to use the tension unit (take-up).
- Possible to low height of the facilities by the chainless type.
- Reduce the garbage by the chainless type.
- Possible to high speed transportation (Max.30m/min.).




### Main Specification

- |                   |                          |
|-------------------|--------------------------|
| ■ Work weight     | Max.100kg                |
| ■ Transfer speed  | Max.30m/min.             |
| ■ Horizontal rail | Min.600mm turning radius |
| ■ Transfer pitch  | 500mm                    |

- Stopper
- Turn device

- Lubricator device
- Index device



**PAT商品**