

Resin Molding Work Transfer series

- : Bumper
- : Inner panel
- : Spoiler

Compelicatedly long size or big work, etc.

Belt Conveyor Type

POINTS

- ◆ Be storage or stock without hitting works which are bumper, locker moal, complecatedly shapes, etc.
- ◆ Just plug in, start to operate Immediately after installation, because for 1-machine by 1-unit. So very easy to change layout or product environment.
- ◆ Belt conveyor width direction fitting with bolt, so can be change easily by work size.(Also we have a width manual adjust by handle.)
- ◆ We can cope the various kinds of works hight for conveyor height, width adjust easily.
- ◆ Can be choose 2-steps, 3-steps type or depending on the purpose space.
- ◆ In comparison with the former machine, a sound is quiet. (Silent product)



Main Specification
Transfer speed
Standard machine long
Belt width
Minimum strage pitch
(at auto)



Max.65m/min.
1 to 13m (about machine long by discuss)
30 to 50mm (different by specification or machine long)
Upper than 100mm



Cat.No.0003

PAT商品

IZUTECH
7S : スリム・スモール・ショート・シンプル・スマート・スピーディ・サイレント
安全・環境保全・低価格・高品質・CS向上